

Philippines **DISASTER RELIEF PROJECT**

Monthly Report - March 2016



PLACEMENT/PROJECT:

Disaster Rehabilitation

PROJECT NAME:

School Building Project

LOCATION:

Barangay Argawanon Integrated School,
Brgy. Argawanon, San Reamegio, Cebu

In March 2016, there were nine volunteers working in the Disaster Rehabilitation Project located in Barangay Argawanon, San Remegio. Volunteers were given separate tasks and guidance from one of the local tradesman. Some volunteers were assigned to paint, guided by the local tradesman (Dante), while the other volunteers were assigned masonry work, guided by the local tradesman (Amid).



A volunteer mixing sand, cement and gravel in preparation for his assigned masonry work, behind the school building.

Considering that all of the volunteers had little experience in construction work, they were closely supervised and advised by the local tradesmen.



A volunteer commencing with the rough finishing work.



A volunteer was guided by the local tradesmen, while commencing rough finishing work.



A volunteer was guided by the local tradesmen, while commencing rough finishing work.



The volunteers, headed by Dante, were assigned the duty of painting preparation. They applied neutralizer on the entire building wall to take out acid and other chemicals present in the cement that could affect the paint.

Volunteers applying a neutralizing agent, to take off the chemicals present in the cement that could affect the paint.

The following day, volunteers started to paint the walls of the building. They were given a specific area of the building to paint, so everyone could work comfortably and without congestion. Some volunteers painted the outside walls of the building, and the others painted the interior walls of the building.



A volunteer applies the first coating of paint on the back of the school building.



A volunteer continues to apply the first coating of paint on the back of the school building.



A volunteer applies the first coating of paint inside the school building.



A volunteer applies a patching compound to cover the cracks of the wall.

Volunteers assigned to paint the outside wall of the building, were required to step up on the wooden scaffolding. A local tradesman was assigned to guide them and he was instructed to secure the scaffolding and watch it closely as the volunteers worked. He made sure to stay close to the volunteers while they were painted, on top of the wooden scaffolding.



Two volunteers apply a coating of paint, on the back wall of the school building.



The volunteers apply a coating of paint, on the back wall of the school building.



The volunteers applied a final coating of paint on the back wall of the school building.

On day 18, volunteers completed their work by painting the entire classroom. They were then transferred to another project site in Anonang Norte Elementary School, Anonang Norte, Bogo City.

The volunteers started pulling out the wall, ceiling and division of the old school building on the 21 March until the end of the month.



Volunteers are guided by the local tradesmen in pulling out the ceiling and the wall of the old school building in Annang Norte Elementary School.



The volunteers working and helping one another in pulling out the wall, ceiling and windows of the old school building in Anonang Norte Elementary School located at Brgy. Anonang Norte, Bogo City, Cebu.